
i1Profiler
Workflow Selector
Display Profiling
Projector Profiling
Printer Profiling
Scanner Profiling
i1 PROFILER
User Mode:
Basic
Advanced
Licensing:
i1Profiler - BASIC 2
Transfer License
i1Profiler
i1Profiler
Workflow Selector
Display
Profiling
Quality
Uniformity
Projector
Profiling
Quality
Printer
Device selection:
CMYK Printer
Workflow selection:
Linearization DEMO
Profiling DEMO
OBC Profiling DEMO
Optimization DEMO
Quality
ColorChecker Proof DEMO
Data Analysis DEMO
Measure Chart
Measure Reference Chart
Device Link Profiling DEMO
User Mode:
Licensing:
Application Settings:


i1Profiler
Thu Jan 22 13:09
i1Profiler
Assets
Display Settings
default-i1Pro.dpxf
Fogra Soft-Proof 2010.dpxf
Profile Settings
default-i1Pro.dpsf
Patch Sets
Measurements
sample-i1Pro.dmxf
ICC Profiles
Saved Workflows
Default Display Settings
Select your display
Color LCD
White Point
CIE Illuminant D65
Luminance
80 cd/m²
100 cd/m²
120 cd/m²
160 cd/m² (ISO 3664 condition P2)
250 cd/m²
Native
Custom...
Measure...
Measurement file
Contrast Ratio
Native
Flare Correct™
Measure and adjust for flare:
Ambient Light Smart Control
Adjust profile based on my ambient light:
Display Settings
Luminance: 120 cd/m2
White Point: x: 0.313 y: 0.329
Page Data
Load
Save
Home
Display Profiling Workflow
118
Display Settings
Profile Settings
Patch set
Measurement
ICC Profile
Display QA
Full Screen
Help
Home
Load Workflow

Profiler

U.S. 98% Thu Jan 22 13:09

i1Profiler

Assets

Settings
default-i1Pro.dpxf
Fogra Soft-Proof 2010.dpxf
ettings
default-i1Pro.dpsf
ts
ments
sample-i1Pro.dmxf
iles
Workflows

Default Display Settings

Select your display

Color LCD

White Point CIE Illuminant D50

Luminance Measure...

...ambient light

Device ready

i1 PRO | CAL | XRGA

Contrast Ratio Native

Flare Correct™

Measure and adjust for flare:

Ambient Light Smart Control

Adjust profile based on my ambient light:

Page Data
Load | Save

Display Settings

Remove the ambient light measuring head from the bottom of the tripod holder, attach it to the i1Pro 2 device then aim the device at the target light source. Click the Measure button when you are ready

Measure

Keep Measurement | Save As... | Cancel

Home Next

Display Profiling Workflow



Display QA

Help Home

Load Workflow Save Workflow


i1Profiler
Thu Jan 22 13:11
i1Profiler
Assets
Settings
default-i1Pro.dpxf
Fogra Soft-Proof 2010.dpxf
Settings
default-i1Pro.dpsf
Sets
rements
sample-i1Pro.dmxf
ofiles
Workflows
Display Settings
Default Display Settings
Select your display
Color LCD
White Point
CIE Illuminant D50
Luminance
Measure...
...ambient light
Device ready
i1 PRO
CAL
XRGA
Contrast Ratio
Native
Flare Correct™
Measure and adjust for flare:
Ambient Light Smart Control
Adjust profile based on my ambient light:
i1Profiler
Save Measurement As:
20140122-LightMeasurement
Cancel
OK
Illuminance: 985.781 lx => Luminance: 168 cd/m2
White Point: x: 0.319 y: 0.336
Measure
Keep Measurement
Save As...
Cancel
Page Data
Load
Save
Home
Next
Display Profiling Workflow
118
Display Settings
Profile Settings
Patch set
Measurement
ICC Profile
Display QA
Help
Home
Load Workflow
Save Workflow


i1 Pro
Back
View
Arrange
Action
Share
Edit Tags
Busines
Colorworks
Search
Search
Name
Date Modified
Size
Kind
20140122-LightMeasurement.cxf
Today, 13:11
2 KB
Document
MacintoshHD ▸ Library ▸ Application Support ▸ X-Rite ▸ AmbientMeasurements ▸ i1 Pro ▸ 20140122-LightMeasurement.cxf
1 of 1 selected, 361.81 GB available

20140122-LightMeasurement.cxf

File Path : /Library/Application Support/X-Rite/AmbientMeasurements/i1 Pro/20140122-LightMeasurement.cxf

20140122-LightMeasurement.cxf (no symbol selected)

```
<?xml version="1.0" encoding="UTF-8"?>
<cc:CxF xmlns:cc="http://colorexchangeformat.com/CxF3-core" xmlns:xsi="http://www.w3.org/2001/XMLSchema-instance">
    <cc:FileInformation>
        <cc:Creator>X-Rite - Prism</cc:Creator>
        <cc:CreationDate>2015-01-22T13:11:02+01:00</cc:CreationDate>
        <cc:Description>Prism CXF3 file</cc:Description>
    </cc:FileInformation>
    <cc:Resources>
        <cc:ObjectCollection>
            <cc:Object ObjectType="Measurement" Name="Measurement1" Id="c1">
                <cc:CreationDate>2015-01-22T13:11:02+01:00</cc:CreationDate>
                <cc:ColorValues>
                    <cc:EmissiveSpectrum StartWL="380" ColorSpecification="XRitePrismDefault">5.619932 6.621193 9.578526 12.045869 1
                </cc:ColorValues>
            </cc:Object>
        </cc:ObjectCollection>
        <cc:ColorSpecificationCollection>
            <cc:ColorSpecification Id="XRitePrismDefault">
                <cc:MeasurementSpec>
                    <cc:MeasurementType>Spectrum_Emissive</cc:MeasurementType>
                    <cc:GeometryChoice>
                        <cc:SingleAngle>
                            <cc:SingleAngleConfiguration>Uniplanar</cc:SingleAngleConfiguration>
                            <cc:IlluminationAngle>0</cc:IlluminationAngle>
                            <cc:MeasurementAngle>45</cc:MeasurementAngle>
                        </cc:SingleAngle>
                    </cc:GeometryChoice>
                    <cc:WavelengthRange StartWL="380" Increment="10"/>
                </cc:MeasurementSpec>
            </cc:ColorSpecification>
        </cc:ColorSpecificationCollection>
    </cc:Resources>
    <cc:CustomResources>
        <xrp:Prism xmlns:xrp="http://www.xrite.com/products/prism" release="2.0">
  <xrp:CustomAttributes Lux="985.781" Tom0_Luminance="168.152"/>
</xrp:Prism>

    </cc:CustomResources>
</cc:CxF>
```

Line 13 Col 1 | XML | Unicode (UTF-8) | Unix (LF) | Last saved: 1/22/15, 13:11:02 | 451 / 44 / 1

Use the freeware TextWrangler editor



Use the grep, search/replace to reformat text



Paste in Excel